

Kolin Philippines International Inc.
1854 Sta. Rita
Makati City
Tel. No. 852-6868

kolin

SERVICE JOB REPORT

No. **0582763**
Backjob SJR No.

Customer	THE GARDENS AT THE GROVE BY ROCKWELL			Date	09/06/2019
Address	E RODRIGUEZ RA VE C5 BRGY UGONG PASIG			Time	03:33pm
Rel. No.	Date of Purchase	Serial No.	Relayed by	Dealer	MARLON (BARISTA)
Model	941-5835	KSG-36C1M	Warranty Type	ISG	
Complaint	AC28 - For Gen. Cleaning		Job Class	GC19	
Remarks	C17/ 09/09 RUFO *ENTRANCE		Job Type	FD	
R No.	Materials		☐ Used	☐ Needed	
Part No.	Description		Qty.	Unit Price	Amount
	General Cleaning indoor				
Findings	Dirty unit			Labor	\$2,500
Repair Done	General Cleaning indoor			Handling	
Repair Code				Total	
Date Attended	9-9-19			Amount Paid	
Time Attended	11:52			Balance	
This serves as temporary receipt when properly filled up by authorized representative				Check No.	
I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Served by: Eupo Mangal Technician			Customer (Signature over printed name)		
Evaluated by: Kevin Rex CRA/Supervisor			Yellow-Guard / Claim Stub		

C-SJR-00-030104

White-Customer

Blue-Accounting

Green-Service

Yellow-Guard / Claim Stub