kolin
Kolin Philippines International Inc.
1854 Sta. Rita, Guadalupe Nuevo
Makati City
Tel. No. 852-6868

SERVICE JOB REPORT

No. 0582762
Backjob SJR No.

Customer	THE GARDENS AT THE GROVE BY ROCKWELL			Date	09/06/2019
Address	E RODRIGUEZ JR AVE C5 BRGY UGONG PASIG			Time	03:32 pm
	09562559169/09178105110/5319535/5763178			Relayed by	MARLON (BARISTA)
Tel. No.	941-5835	Date of Purchase		Dealer	ISG
Model	KSG-36C1M	Serial No.	10501506-11145	Warranty Type	C
Complaint	AC28 - For Gen. Cleaning			Job Class	GC
Remarks	C17/ 09/09 RUFO *ENTRANCE			Job Type	FD
SR No.		Materials ☐ Used ☐ Needed			

Part No.	Description	Qty.	Unit Price	Amount

Findings	dirty unit	Labor	₱ 2,500
		Handling	
Repair Done	General cleaning indoor & outdoor	Total	
Repair Code		Amount Paid	for collection need soa
		Balance	
		Check No.	

Date Attended	9-9-19	Date Finished	9-9-19
Time Attended	11:55	Time Finished	3:25

This serves as temporary receipt when properly filled up by authorized representative

Serviced by: Rufo, Marlon, Kevin, Rex
Technician

Evaluated by: CHER
CRA/Supervisor

I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.

Customer
(Signature over printed name)

SVC-SJR-00-030104 White-Customer Blue-Accounting Green-Service Yellow-Guard / Claim Stub