

Kolin Bldg. 1854 Sta. Rita St.,
Guadalupe Nuevo, Makati City

DAILY SJR: BROUGHT-IN/ PULL-OUT FOR SHOP REPAIR

STATUS: BILLED

DATE : FEBRUARY 17, 2020 (MONDAY)

DATE :	SJR	C U S T O M E R	M O D E L	REPAIR DONE	TOTAL CHARGE	WTY. TYPE	JOB TYPE	DATE/TIME RECEIVED	DATE/TIME BILLED
14-Feb-20	HO-9908	PUIG, GARIE	KLE-43DTE32	CHECK-UP	250.00	C	BI	2/17/20 2:07 PM	2/17/20 1:54 PM
08-Feb-20	HO-9173	CASTRO II, RAMON A.	KAG-11RE	GC W/MAJOR	3,660.00	C	BI	2/17/20 2:11 PM	2/17/20 2:30 PM
28-Jan-20	HO-7441	STESSO SLIMMING & FACIAL CENTER	KDM-20LES	REPAIR OF UNIT	-	W	BI	2/17/20 2:11 PM	2/17/20 2:36 PM

PREPARED BY :

J. A. Lominoque
2/17

JELYN A. LOMINOQUE

SVC ACCTG ASST.

NOTED BY :

Richell V. Hicban
2/17/2020

RICHELL V. HICBAN

SVC ACCTG ASST. SUPERVISOR

RECEIVED BY :

Ruben Buena
2/17/2020 2:50 PM

RUBEN BUENA

SERVICE WAREHOUSE CLERK