

Kolin Bldg. 1854 Sta. Rita St.,
Guadalupe Nuevo, Makati City

DAILY SJR: BROUGHT-IN/ PULL-OUT FOR SHOP REPAIR

STATUS: BILLED

DATE : FEBRUARY 20, 2020 (THURSDAY)

DATE :	SJR	C U S T O M E R	MODEL	REPAIR DONE	TOTAL CHARGE	WTY. TYPE	JOB TYPE	DATE/TIME BILLED	DATE/TIME RECEIVED
14-Feb-20	HO-9872	NAVAL, RODILO	KAG-150HRE4	SYSTEM REPROCESS	-	W	PO	2/20/20 9:13 AM	2/20/20 9:00 AM
12-Feb-20	HO-9621	VILLAMORE, MERYLL	KAG-110RSINV	SYSTEM REPROCESS	-	W	PO	2/20/20 9:07 AM	2/20/20 9:00 AM

PREPARED BY :

J. A. Lominoque
JELYN A. LOMINOQUE
SVC ACCTG ASST.

9:28

NOTED BY :

Richell V. Hicban
RICHELL V. HICBAN
SVC ACCTG ASST. SUPERVISOR

RECEIVED BY :

Michael Angelo B. Gana
MICHAEL ANGELO B. GANA
CALL TAKER

9:30am