

Kolin Bldg. 1854 Sta. Rita St.,
Guadalupe Nuevo, Makati City

DAILY SJR: BROUGHT-IN/ PULL-OUT FOR SHOP REPAIR

STATUS: BILLED

DATE : FEBRUARY 21, 2020 (FRIDAY)

DATE :	SJR	C U S T O M E R	M O D E L	R E P A I R D O N E	T O T A L C H A R G E	W T Y . T Y P E	J O B T Y P E	D A T E / T I M E B I L L E D	D A T E / T I M E R E C E I V E D
17-Feb-20	HO-10306	DAJOTOY, ANJIE	KAG-110RSINV	SYSTEM REPROCESS	-	W	PO	2/21/20 8:40 AM	2/21/20 8:37 AM
15-Feb-20	HO-10047	RABINO, MARICAR	KAG-110RSINV	SYSTEM REPROCESS	-	W	PO	2/21/20 8:45 AM	2/21/20 8:37 AM

PREPARED BY :

JELYN A. LOMINOQUE

SVC ACCTG ASST.

NOTED BY :

RICHIE V. HICBAN

SVC ACCTG ASST. SUPERVISOR

RECEIVED BY :

MICHAEL ANGELO B. GANA

CALL TAKER