

Kolin Bldg. 1854 Sta. Rita St.,
Guadalupe Nuevo, Makati City

DAILY SJR: BROUGHT-IN/ PULL-OUT FOR SHOP REPAIR

STATUS: BILLED

DATE : JUNE 10, 2020 (WEDNESDAY)

DATE :	SJR	CUSTOMER	MODEL	REPAIR DONE	TOTAL CHARGE	WTY. TYPE	JOB TYPE	DATE/TIME RECEIVED	DATE/TIME BILLED
04-Jun-20	HO-18709	UBILLA, NELSON	KSG-30B1M	REFUSED TO REPAIR	-	C	BI	6/10/20 9:31 AM	6/10/20 9:45 AM

PREPARED BY : *9:50*
4/10

NOTED BY : *4/10*
RICHIE V. HICBAN

RECEIVED BY : *6/10/20 10:47*
RUBEN BUENA
SERVICE WAREHOUSE CLERK

Kolin Bldg. 1854 Sta. Rita St.,
Guadalupe Nuevo, Makati City

DAILY SJR: BROUGHT-IN/ PULL-OUT FOR SHOP REPAIR
STATUS: BILLED

DATE : JUNE 10, 2020 (WEDNESDAY)

DATE :	SJR	CUSTOMER	MODEL	REPAIR DONE	TOTAL CHARGE	WTY. TYPE	JOB TYPE	DATE/TIME RECEIVED	DATE/TIME BILLED
27-May-20	HO-17297	HASAAAN KABAB & STEAKS INC.	KSM-20MB1INV	REFUSED TO REPAIR	500.00	C	PO	6/10/20 9:31 AM	6/10/20 9:40 AM

PREPARED BY : *9:50*
4/10
JELYN A. LOMINOQUE
SVC ACCTG ASST.

NOTED BY : *4/10*
RICHIE V. HICBAN
SVC/ACCTG ASST. SUPERVISOR

RECEIVED BY : *6/10/20 10:46*
MICHAEL ANGELO B. GANA
CALL TAKER