

Kolin Bldg. 1854 Sta. Rita St.,
Guadalupe Nuevo, Makati City

DAILY SJR: BROUGHT-IN/ PULL-OUT FOR SHOP REPAIR

STATUS: BILLED

DATE: JUNE 15, 2020 (MONDAY)

DATE :	SJR	C U S T O M E R	M O D E L	REPAIR DONE	TOTAL CHARGE	WTY. TYPE	JOB TYPE	DATE/TIME RECEIVED	DATE/TIME BILLED
08-Jun-20	HO-19473	RAPSING MANUEL	SLE-42EMA30	CHECK-UP	400.00	C	BI	6/15/20 3:21 PM	6/15/20 3:33 PM

PREPARED BY :

J. C. 6/15
JELYN A. LOMINOQUE
SVC ACCTG ASST.

NOTED BY :

Rubickson 6/15
RICHELL V. HICBAN
SVC/ACCTG ASST. SUPERVISOR

RECEIVED BY :

For: D. 6/15 1:42
RUBEN BUENA
SERVICE WAREHOUSE CLERK