

Kolin Bldg. 1854 Sta. Rita St.,
Guadalupe Nuevo, Makati City

DAILY SJR: BROUGHT-IN/ PULL-OUT FOR SHOP REPAIR

STATUS: BILLED

DATE : JUNE 2, 2020 (TUESDAY)

DATE :	SJR	C U S T O M E R	MODEL	REPAIR DONE	TOTAL CHARGE	WTT. TYPE	JOB TYPE	DATE/TIME RECEIVED	DATE/TIME BILLED
29-May-20	HO-17760	GANTUIN, ROMEO	KAG-150RSINV	SYSTEM REPROCESS	440.00	C	PO	6/2/20 9:00 AM	6/2/20 10:48 AM
23-May-20	HO-16973	GANTUIN, ROMEO	KAG-150RSINV	SYSTEM REPROCESS	5,950.00	C	PO	6/2/20 9:00 AM	6/2/20 10:47 AM
13-May-20	HO-15619	CUENO, KAYE	KAG-150RSINV	SYSTEM REPROCESS	2,965.00	C	PO	6/2/20 9:00 AM	6/2/20 10:40 AM
26-May-20	HO-17032	JOCSON, AJHON	KSM-1W15-4H1M	SYSTEM REPROCESS	4,915.00	C	PO	6/2/20 9:00 AM	6/2/20 10:30 AM
28-May-20	HO-17614	MARIANO, LORD AARON	KAG-100HME4	SYSTEM REPROCESS	-	W	PO	6/2/20 9:00 AM	6/2/20 10:29 AM
19-May-20	HO-16042	CHHATTANI, JYOTI	KAG-150RSINV	SYSTEM REPROCESS	-	W	PO	6/2/20 9:00 AM	6/2/20 10:27 AM
27-May-20	HO-17293	BADIOLA, BRYAN JOSE	KSM-1W15AE-5G1M	SYSTEM REPROCESS	4,300.00	C	PO	6/2/20 9:00 AM	6/2/20 9:59 AM
20-May-20	HO-16297	VIOLA, JUN	KAG-150RSINV	SYSTEM REPROCESS	7,165.65	W	PO	6/2/20 9:00 AM	6/2/20 9:55 AM

PREPARED BY :

JELYN A. DOMINQUE
SVC ACCTG ASST.

NOTED BY :

RICHIELL V. HICBAN
SVC ACCTG ASST. SUPERVISOR

RECEIVED BY :

MICHAEL ANGELO B. GANA
CALL TAKER