

Kolin Bldg. 1854 Sta. Rita St.,
Guadalupe Nuevo, Makati City

DAILY SJR: BROUGHT-IN/ PULL-OUT FOR SHOP REPAIR

STATUS: BILLED

DATE : JUNE 8, 2020 (MONDAY)

DATE :	SJR	C U S T O M E R	MODEL	REPAIR DONE	TOTAL CHARGE	WTY. TYPE	JOB TYPE	DATE/TIME RECEIVED	DATE/TIME BILLED
21-May-20	HO-16498	GALAROZA, MELLY	KSM-10MB1INV	SYSTEM REPROCESS	7,036.50	C	PO	6/8/20 3:10 PM	6/8/20 3:46 PM
06-Jun-20	HO-19086	NG, OLIVIA CHUA	REMOTE	CHECK-UP	-	L	PO	6/8/20 3:10 PM	6/8/20 3:26 PM
02-Jun-20	HO-18365	ACASA, PROPERTY CORP.	KAG-200HME4	SYSTEM REPROCESS	-	W	PO	6/8/20 3:10 PM	6/8/20 3:57 PM

PREPARED BY :

4/24
4/24

NOTED BY :

Rubicon 6/8/20

RECEIVED BY :

6/8/20 4:09

Kolin Bldg. 1854 Sta. Rita St.,
Guadalupe Nuevo, Makati City

DAILY SJR: BROUGHT-IN/ PULL-OUT FOR SHOP REPAIR

STATUS: BILLED

DATE : JUNE 8, 2020 (MONDAY)

DATE :	SJR	C U S T O M E R	MODEL	REPAIR DONE	TOTAL CHARGE	WTY. TYPE	JOB TYPE	DATE/TIME RECEIVED	DATE/TIME BILLED
21-May-20	HO-16523	CHAVEZ, GIL	LED-TV	MAJOR REPAIR	-	W	BI	6/8/20 3:10 PM	6/8/20 3:41 PM

PREPARED BY :

4/24
4/24
JELYN A. LOMINOQUE
SVC/ACCTG ASST.

NOTED BY :

Rubicon 6/8/20
RICHELL V. HICBAN
SVC/ACCTG ASST. SUPERVISOR

RECEIVED BY :

6/8/20 4:09
RUBEN BUENA
SERVICE WAREHOUSE CLERK