

Kolin Bldg. 1854 Sta. Rita St.,  
Guadalupe Nuevo, Makati City

DAILY SJR: BROUGHT-IN/ PULL-OUT FOR SHOP REPAIR

STATUS: BILLED

DATE: JUNE 9, 2020 (TUESDAY)

| DATE :    | SJR      | CUSTOMER           | MODEL        | REPAIR DONE      | TOTAL CHARGE | WTY. TYPE | JOB TYPE | DATE/TIME RECEIVED | DATE/TIME BILLED |
|-----------|----------|--------------------|--------------|------------------|--------------|-----------|----------|--------------------|------------------|
| 28-May-20 | HO-17606 | CAPISTRANO, NORBEL | KAG-110RSINV | GENERAL CLEANING | 1,209.00     | C         | PO       | 6/9/20 3:14 PM     | 6/9/20 3:25 PM   |

PREPARED BY :

15:30

JELYN A. LOMINOQUE

SVC ACCTG ASST.

NOTED BY :

Richell V. HICBAN

SVC ACCTG ASST. SUPERVISOR

RECEIVED BY :

MICHAEL ANGELO B. GANA

CALL TAKER

3:37