

Kolin Bldg. 1854 Sta. Rita St.,
Guadalupe Nuevo, Makati City

DAILY SJR: BROUGHT-IN/ PULL-OUT FOR SHOP REPAIR

STATUS: BILLED

DATE: MARCH 13, 2020 (FRIDAY)

DATE :	SJR	C U S T O M E R	M O D E L	REPAIR DONE	TOTAL CHARGE	WTV. TYPE	JOB TYPE	DATE/TIME RECEIVED	DATE/TIME BILLED
04-Mar-20	HO-12804	VIVERO, ANTHONY	KAG-150HRE4	SYSTEM REPROCESS	-	W	PO	3/13/20 2:11 PM	3/13/20 2:36 PM
09-Mar-20	HO-13758	CRISTOBAL, LOUIE GABRIEL	KAG-110RSINV	SYSTEM REPROCESS	6,390.00	C	PO	3/13/20 2:11 PM	3/13/20 2:30 PM
04-Mar-20	HO-12800	DE LEON, AMELITTA	KSG-20B1	SYSTEM REPROCESS	6,368.50	C	PO	3/13/20 2:11 PM	3/13/20 2:25 PM

PREPARED BY :


JELYN A. LOMINOQUE
SVC ACCTG ASST.
2:45

NOTED BY :


RICHELL V. HICBAN
SVC ACCTG ASST. SUPERVISOR
3/13

RECEIVED BY :


MICHAEL ANGELO B. GANA
CALL TAKER
3-13-2020 2:50 PM