

Kolin Bldg. 1854 Sta. Rita St.,
Guadalupe Nuevo, Makati City

DAILY SJR: BROUGHT-IN/ PULL-OUT FOR SHOP REPAIR

STATUS: BILLED

DATE : MARCH 05, 2020 (THURSDAY)

DATE :	SJR	C U S T O M E R	M O D E L	R E P A I R D O N E	T O T A L C H A R G E	W T Y . T Y P E	J O B T Y P E	D A T E / T I M E R E C E I V E D	D A T E / T I M E B I L L E D
27-Feb-20	HO-11783	LIRIO, RENATO	KDM-20DGS	SYSTEM REPROCESS	7,000.00	C	BI	3/5/20 11:31 AM	3/5/20 11:43 AM
28-Feb-20	HO-11932	SOLIS, MARK CHRISTIAN	SLE-4093KMD	REPAIR OF UNIT	1,000.00	C	BI	3/5/20 3:21 PM	3/5/20 3:30 PM

PREPARED BY :

3/5
JELYN A. LOMINOQUE
SVC ACCTG ASST.

NOTED BY :

3/5
RICHELL V. HICBAN
SVC ACCTG ASST. SUPERVISOR

RECEIVED BY :

for 3/5/2020 3:42
RUBEN BUENA
SERVICE WAREHOUSE CLERK