

Kolin Bldg. 1854 Sta. Rita St.,  
Guadalupe Nuevo, Makati City

DAILY SJR: BROUGHT-IN/ PULL-OUT FOR SHOP REPAIR

STATUS: BILLED

DATE : FEBRUARY 6, 2020 (THURSDAY)

| DATE :    | SJR     | C U S T O M E R        | M O D E L  | REPAIR DONE      | TOTAL<br>CHARGE | WTY.<br>TYPE | JOB<br>TYPE | DATE/TIME<br>BILLED | DATE/TIME<br>RECEIVED |
|-----------|---------|------------------------|------------|------------------|-----------------|--------------|-------------|---------------------|-----------------------|
| 06-Feb-20 | HO-8876 | KOLIN PHIL. INT'L INC. | KFS-35DINV | SYSTEM REPROCESS | -               | W            | BI          | 2/10/20 8:40 AM     | 2/10/20 9:49 AM       |

PREPARED BY :

*Jelynn A. Lominoque* 10:24  
JELYN A. LOMINOQUE  
SVC ACCTG ASST.

NOTED BY :

*Richell V. Hicban* 2/10/2020  
RICHELL V. HICBAN  
SVC ACCTG ASST. SUPERVISOR

RECEIVED BY :

*Ruben Buena* 2/10/2020 10:29 AM  
RUBEN BUENA  
SERVICE WAREHOUSE CLERK