

Kolin Bldg. 1854 Sta. Rita St.,
Guadalupe Nuevo, Makati City

DAILY SJR: BROUGHT-IN/ PULL-OUT FOR SHOP REPAIR

STATUS: BILLED

DATE : FEBRUARY 3, 2020 (MONDAY)

DATE :	SJR	C U S T O M E R	M O D E L	REPAIR DONE	TOTAL CHARGE	WTY. TYPE	JOB TYPE	DATE/TIME BILLED	DATE/TIME RECEIVED
16-Jan-20	HO-5803	CENTER STAGE MOA	KFM-400F1J	SYSTEM REPROCESS	21,469.05	C	PO	2/3/20 11:57 AM	2/3/20 11:31 AM
23-Jan-20	HO-6834	ESGUERRA, ANNALYN	KAG-110RSINV	SYSTEM REPROCESS	-	W	PO	2/3/20 12:00 PM	2/3/20 11:31 AM

PREPARED BY :

13:12

JELYN A. LOMINOQUE

SVC ACCTG ASST.

NOTED BY :

Richell V. Hicban 2/3/2020

RICHELL V. HICBAN

SVC ACCTG ASST. SUPERVISOR

RECEIVED BY :

2/3/2020 1:18 pm

MICHAEL ANGELO B. GANA

CALL TAKER