

FEBRUARY 18, 2020

MONANI, LINA 31 SAN MATTIN, MAGALLANES VILL., MAKATI CITY, METRO MANILA 0917-5496630 7967-6630

Sir/Ma'am;

Kindly see the quotation below for more details.

MODEL: KAG-150DME

SJR: HO-10249

Part Code:	Parts Description	Qty.	Amount	Fotal Amount
GR01001305	Evaporator	1	3,300.00	3,300.00
Repair Code	Repair Done			Labor
WAC05	System Reprocess with General Cleaning			2,600.00
HND02	Pulled-out Delivery			500.00
	Total:			6,400.00

Total Initial Charge:

less Check up fee \$450.00 Rep Lir

OR# 120719

Note:

- 1. Upon receiving a quotation, please check the details. To proceed with the repair we need your confirmation with 50% downpayment.
- 2. Kindly reminded that you must comply in 2 working days otherwise your unit will be considered refuse to repair hence, your unit will delivered back un-repaired with fitting charges.
- 3. Repaired units are guaranteed for a period of 90 days (Parts & Labor) from date of unit acceptance and for the same encountered defects.
- 4. Please be informed that upon delivery and installation of your unit the remaining balance of 50% shall be paid to our installer or technician.
- 5. If you need assistance and update don't hesitate to call the under signed (Angel Arlan De Torres at (8)962-5610 or 0917-806-0920).
- 6. For replacement of Evaporator.

7. Initial Quotation.

Prepared by:

BRYAN JED O. ARCILLA SERVICE ACCOUNTING ASST.

Noted by:

SHOP FOREMAN

Received by:

SHOP ASSISTANT

Conforme by:

SIGNATURE OVER PRINTED NAME

Head Office:

1854 Sta. Rita St., Guadalupe Nuevo, Makati City www.kolinphil.com.ph

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant:

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy,

Langkaan I, Dasmariñas, Cavite Tel.: (632) 749-2118

Fax: (046) 402-0793

