

**FEBRUARY 18, 2020** 

MATIC, HAIDEE 2827 J. CONANAN ST., BRGY. 183 GAGALANGIN, TONDO I/II, MANILA 0923-5354588 8255-8492

Sir/Ma'am;

Kindly see the quotation below for more details.

**MODEL: KAG-110RSINV** 

SJR: HO-10312

Part Code:	Parts Description Qty	Amount	<b>Total Amount</b>
GR0110010278	Evaporator 1	3,300.00	3,300.00
Repair Code	Repair Done		Labor
WAC05	System Reprocess with General Cleaning	2,600.00	
HND02	Pulled-out Delivery	500.00	
	Total:	6,400.00	

Total Initial Charge:		100	P	6,400.00
TOTAL MARKET CAME BY			Management	

## Note:

1. Upon receiving a quotation, please check the details. To proceed with the repair we need your confirmation with 50% downpayment.

2. Kindly reminded that you must comply in 2 working days otherwise your unit will be considered refuse to repair hence, your unit will delivered back un-repaired with fitting charges.

3. Repaired units are guaranteed for a period of 90 days (Parts & Labor) from date of unit acceptance and for the same encountered defects.

4. Please be informed that upon delivery and installation of your unit the remaining balance of 50% shall be paid to our installer or technician.

5. If you need assistance and update don't hesitate to call the under signed (Angel Arlan De Torres at (8)962-5610 or 0917-806-0920).

6. For replacement of Evaporator.

7. Initial Quotation.

Prepared by:

Noted by:

BRYAN JED O. ARCILLA

SERVICE ACCOUNTING ASST.

TOPL II CORTA

SHOP FOREMAN

Received by

ANGEL ARLAN A. DE TORRE

SHOP ASSISTANT

Conforme by:

" lia [mai/ /2. 20. 20 /9:15

CUSTOMER NAME

SIGNATURE OVER PRINTED NAME

Head Office:

1854 Sta. Rita St., Guadalupe Nuevo, Makati City www.kolinphil.com.ph

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant:

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy, Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793