

FEBRUARY 20, 2020

FLORENDO, DENNIS  
33B CAVALRY HILLS, ROLLING HILLS SUBD., BRGY., DAMAYANG LAGI  
NEW MANILA, QUEZON CITY, METRO MANILA  
0917-3004298

Sir/Ma'am;

Kindly see the quotation below for more details.

MODEL: KAG-200RSINV

SJR: HO-10467

Part Code:	Parts Description	Qty	Amount	Total Amount
GR0110010312	Evaporator	1	4,400.00	4,400.00
GR1020005	Capacitor 7uF/450V	1	220.00	220.00
Repair Code	Repair Done	Labor		
WAC05	System Reprocess with General Cleaning			2,600.00
Total:				7,220.00

Total Initial Charge:

P 7,220.00

**Note:**

1. Upon receiving a quotation, please check the details. To proceed with the repair we need your confirmation with 50% downpayment.
2. Kindly reminded that you must comply within 2 working days otherwise your unit will be considered refuse to repair hence, your unit will delivered back un-repaired with fitting charges.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. For brought-in units, please be informed that your remaining balance of 50% shall be paid to our Customer Service Clerk.
5. If you need assistance and update don't hesitate to call the under signed (*Angel Arlan De Torres at (8)962-5610 or 0917-806-0920*).
6. For replacement of Evaporator and Capacitor.
7. Initial Quotation.

Prepared by:

*B. Arcilla 2/20*  
BRYAN JED O. ARCILLA  
SERVICE ACCOUNTING ASST.

Received by:

*Angel Arlan A. De Torres 2/20*  
ANGEL ARLAN A. DE TORRES  
SHOP ASSISTANT

Noted by:

*Joel U. Coria*  
JOEL U. CORIA  
SHOP FOREMAN

Conforme by:

*Dennis Florendo 2/20 9:53 AM*  
CUSTOMER NAME  
SIGNATURE OVER PRINTED NAME

Head Office:

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

www.kolinphil.com.ph

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4701

Kolin Plant:

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy,

Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 403 0702