

KOLIN PHILIPPINES INTERNATIONAL INC.

1854 Sta. Rita St., Guadalupe Nuevo,

1212 Makati City

EMAIL ADDRESS: inhouse.shop@kolinphil.com.ph

TEL.: (02)8-9625610

MOBILE: (+63)9178060920

Prepared by: Bryan Jed O. Arcilla - Service Accounting Assistant

kolin
air conditioner**REPAIR COST ESTIMATE****CUSTOMER:****BADIOLA, BRYAN JOSE**

UNIT 2160 TOWER 2 SMDC GRACE RESIDENCES, CAYETANO ST.,

BRGY. USUSAN, TAGUIG CITY, METRO MANILA

PHONE: 0998-8521650

DATE:	MAY 29, 2020
SJR #:	HO-17293
MODEL:	KSM-IW15AE-5G1M

TERMS AND CONDITION

1. The repair will proceed after indicating acceptance of this quote with 50% downpayment.
2. Customer shall conform within 2 working days otherwise unit will be considered refuse to repair hence, unit will be delivered back un-repaired with fitting charges.
3. Kindly deposit your 50% down-payment to the following bank account: Reference SJR# HO-17293

BDO

Account Name: Kolin Philippines International Inc.

Account Number: 0118-0800-0428

BPI

Account Name: Kolin Philippines International Inc.

Account Number: 3531-00-4468

4. Should any additional work or materials be found necessary in the course of these repairs or subsequent testing, it will be necessary to make an extra charge. Where this additional work involves a substantial increase in the amount estimated, a supplementary estimate will be submitted for acceptance.
5. Repaired units are guaranteed for a period of 90 days (**Parts & Labor**) from date of unit acceptance and for the same encountered defects.
6. If you have any questions about this price quote, please contact under signed *Angel Arlan De Torres* at (02)8-9625610 or (+63)9178060920 and "inhouse.shop@kolinphil.com.ph".
7. Payment of remaining 50% balance will be due upon delivery/pick-up of unit.
8. Please email the signed price quote to the address above.

Customer Acceptance and return. (sign below)

x Via Email 5.29.20 11:15 w/ ATTACHMENT DP

Print Name:


DESCRIPTION	AMOUNT
[LABOR] System Reprocess with General Cleaning (1.0hp-3.0hp)	P 4,250.00
[PARTS] Compressor	P 0.00
HANDLING FEE WITHIN METRO MANILA	P 500.00

SUBTOTAL: P 4,750.00


PAID HANDLING FEE: P 450.00

GRAND TOTAL: P 4,300.00

Received by:


ANGEL ARLAN A. DE TORRES
SHOP ASSISTANT

Noted by:


JOEL U. CORIA
SHOP FOREMAN

Head Office:

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

www.kolinphil.com.ph

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant:

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy,

Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793



Step 3 of 3 - Transfer money was successful!

Transfer from:

CHECKING ACCOUNT | 5275059333

↑ Transfer Amount PHP 2,150.00

! Service fee PHP 0.00

Total amount deducted:

↑ PHP 2,150.00

☰ Bryan Badiola - 50 percent DP for kolin repair

Transfer to:

3531004468

✓ Mobile key approved

Transfer money was successful!

Confirmation Date & Time: Friday, May 29 2020;

11:13:44 AM (GMT +8)

Confirmation Number: 1590722020706

17295
Badiola, Bryan Jose