

**KOLIN PHILIPPINES INTERNATIONAL INC.**

1854 Sta. Rita St., Guadalupe Nuevo,

1212 Makati City

EMAIL ADDRESS: [inhouse.shop@kolinphil.com.ph](mailto:inhouse.shop@kolinphil.com.ph)

TEL.: (02)8-9625610

MOBILE: (+63)9178060920

Prepared by: Bryan Jed O. Arcilla - Service Accounting Assistant

**kolin**  
air conditioner**REPAIR COST ESTIMATE****CUSTOMER:****GUILLIDO, MICHAEL**

ROYAL PALM RESIDENCES, KARON 214, ACACIA ESTATES,

TAGUIG CITY, METRO MANILA

PHONE: 0917-8446955

DATE:	JUNE 05, 2020
SJR #:	HO-18719
MODEL:	KAG-80DRE

**TERMS AND CONDITION**

1. The repair will proceed after indicating acceptance of this quote with 50% downpayment.
2. Customer shall conform within 2 working days otherwise unit will be considered refuse to repair hence, unit will be delivered back un-repaired with fitting charges.
3. Kindly deposit your 50% down-payment to the following bank account: Reference SJR# HO-18719

**BDO**

Account Name: Kolin Philippines International Inc.

Account Number: 0118-0800-0428

**BPI**

Account Name: Kolin Philippines International Inc.

Account Number: 3531-00-4468

4. Should any additional work or materials be found necessary in the course of these repairs or subsequent testing, it will be necessary to make an extra charge. Where this additional work involves a substantial increase in the amount estimated, a supplementary estimate will be submitted for acceptance.
5. Repaired units are guaranteed for a period of 90 days (**Parts & Labor**) from date of unit acceptance and for the same encountered defects.
6. If you have any questions about this price quote, please contact under signed **Angel Arlan De Torres** at (02)8-9625610 or (+63)9178060920 and "[inhouse.shop@kolinphil.com.ph](mailto:inhouse.shop@kolinphil.com.ph)".
7. Payment of remaining 50% balance will be due upon delivery/pick-up of unit.
8. Please email the signed price quote to the address above.

Customer Acceptance and return. (sign below)

x

*via Email / 6.5.20 / 12:27 PM w/ attachment pr*

Print Name:


DESCRIPTION	AMOUNT
[LABOR] System Reprocess with General Cleaning	P 2,600.00
[PARTS] EVAPORATOR	P 2,244.00
[PARTS] CAPACITOR 3.5UF/450V	P 165.00
[PARTS] BEARING 6201 [2 PCS]	P 440.00
HANDLING FEE WITHIN METRO MANILA	P 500.00

SUBTOTAL: P 5,949.00


PAID CHECK-UP FEE: P 450.00

**GRAND TOTAL: P 5,499.00**

Received by:

  
**ANGEL ARLAN A. DE TORRES**  
SHOP ASSISTANT

Noted by:

  
**JOEL U. CORIA**  
SHOP FOREMAN

Head Office:

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

[www.kolinphil.com.ph](http://www.kolinphil.com.ph)

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant:

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy,

Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793



**KOLIN PHILIPPINES INTERNATIONAL INC.**

1854 Sta. Rita St., Guadalupe Nuevo,

1212 Makati City

EMAIL ADDRESS: inhouse.shop@kolinphil.com.ph

TEL.: (02)8-9625610

MOBILE: (+63)9178060920

Prepared by: Bryan Jed O. Arcilla - Service Accounting Assistant

**ACCOUNTING REFERENCE****CUSTOMER:****GUILLIDO, MICHAEL**

ROYAL PALM RESIDENCES, KARON 214, ACACIA ESTATES,

TAGUIG CITY, METRO MANILA

PHONE: 0917-8446955

<b>DATE:</b>	<b>JUNE 09, 2020</b>
<b>SJR #:</b>	<b>HO-18719</b>
<b>MODEL:</b>	<b>KAG-80DRE</b>

<b>DESCRIPTION</b>	<b>AMOUNT</b>
[LABOR] System Reprocess with General Cleaning	₱ 2,600.00
[PARTS] EVAPORATOR	₱ 2,244.00
[PARTS] CAPACITOR 3.5UF/450V	₱ 165.00
[PARTS] BEARING 6201 [2 PCS]	₱ 440.00
HANDLING FEE WITHIN METRO MANILA	₱ 500.00

SUBTOTAL: ₱ 5,949.00

HO-17739

PAID CHECK-UP FEE: ₱ 450.00

DOWNPAYMENT: THROUGH BDO MOBILE BANKING: ₱ 2,749.50

**BALANCE: ₱ 2,749.50**