

NOVEMBER 8, 2019

MNM TRADING

#78 BRIXTON HILLS BRGY. SANTOL QUEZON CITY 8713-5268  
713-5268

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KAG-260RS

SJR: 0591269

Parts	Amount
Anti Freeze	220.00 /
Fan Capacitor	220.00 /
Metal Partition (Condenser Side)	880.00 /
System Reprocess	2,000.00
Pull Out Delivery	<u>500.00</u>
Total:	3,820.00

Total Estimated Charge:

P 3,820.00

Note:

1. Replacement Of Anti Freeze, Fan Capacitor, Metal Partition (Con-Side)
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at **852-6868 or 0917-806-0920.**
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair. However, problem(s) may occur once after or during replacement of part(s).
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. Initial Quotation.

Prepared by:

ANGEL ARLAN DE TORRES  
SHOP ASSISTANT

Noted by:

JOEL CORIA  
SHOP FOREMAN

Conforme:

SIGNATURE OVER PRINTED NAME

Head Office

1054 Sta. Rita St. Guadalupe Nuevo Makati City  
www.kolinphil.com.ph

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy.  
Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793

2:41 PM

11-9-19