

December 10, 2019

ALCAZAR LEA
#271-B MANUEL L. QUEZON ST. BAGONG BAYAN
TAGUIG CITY 0922-8231153
0922-8231153

Sir/Ma'am:

Please find below the quotation for repair of the following unit:

KAG-190DMF	SJR- 0587594
Parts	Amount
Fan Capacitor	165.00
Compressor Capacitor	385.00
Service unit Fee	250.00
Labor	1.00
Phil. Old 2800.00	
Total	800.00
Total Estimated Charge:	P 800.00


Note:

1. Replacement Of Compressor Capacitor, Fan Capacitor.
2. Unit charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (Parts & Labor) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (Angel Arlan De Torres) at 852-6868 or 0917-806-0920.
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair.
6. The balance 50% downpayment will be paid to Kolin Philippines before the unit.
7. The Warranty of the unit will be shouldered by Kolin Philippines Int'l Inc. Head office.
8. Initial Quotation

Prepared by: 
ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by: 
JOEL CORIA
SHOP FOREMAN

A NOTE: ANY UNIT PROBLEM THAT NOT OCCUR AFTER THIS REPAIR, KOLIN PHILIPPINES WILL NOT BE HELD LIABLE THEREAFTER.

Conformed by: 
JULIE FLORES, UICHL 12/10/19
SIGNATURE OVER PRINTED NAME

12.10.19/10:18 AM

Head Office:
Kolin Plaza, 1st Floor, 1000 N. Alameda Ave., Makati City
www.kolinph.com.ph
Tel: (632) 851-2711, 12 or 13
Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant:
1000 N. Alameda Ave., 1st Floor, Makati City
Lungsod ng Marikina, Cavite
Tel: (632) 449-2118
Fax: (046) 402-0793

c/o Enthalphy