

JANUARY 10, 2020

NUÑEZ, IMELDA  
BLK. 2 LOT 17 PINAGSAMA VILLAGE TAGUIG  
0919-0653063

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KAG-110RSINV

SJR: HO-4496

Parts

Amount

System Reprocess

2,000.00

Total:

2,000.00

Total Estimated Charge:

P 2,000.00


**Note:**

1. *Unit For System Reprocess.*
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at **852-6868 or 0917-806-0920.**
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair. However, problem(s) may occur once after or during replacement of part(s).
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. *Initial Quotation.*

Prepared by:

  
ANGEL ARLAN DE TORRES  
SHOP ASSISTANT

Noted by:

  
JOEL CORIA  
SHOP FOREMAN

Conforme:

  
SIGNATURE OVER PRINTED NAME