

OCTOBER 25, 2019

ORUGA, ARMI C/O GREAT START SIT'L SCHOOL
187 DOÑA SOLEDAD EXTN. BETTER LIVING SUBD.
BRGY. DON BOSCO PARAÑAQUE 0998-9995437
824-2238

Sir/Ma'am:

Please find below the quotation for repair of the following unit.

MODEL: KSM-20MB11NV

SJR: 0589455

Parts

Amount

Compressor

14,300.00

System Reprocess

3,500.00

Pull Out Delivery

500.00

Total:

14,000.00

Total Estimated Charge:

P 14,000.00

Note:

1. *Replacement Of Compressor.*

2. Final charges will be based on actual repair of unit.

3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.

4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at 852-6868 or 0917-806-0920.

5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair. However, problem(s) may occur once after or during replacement of part(s).

6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.

7. *Initial Quotation.*

Prepared by:

ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:

JOEL CORIA
SHOP FOREMAN

Conforme:

Via Email / 11-11-19 / 9:50 PM

SIGNATURE OVER PRINTED NAME

NATIONAL SERVICE MANAGER

Head Office:

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

www.kolinphil.com.ph

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant:

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy.

Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793

Considered Warranty

₱ 14,000.00

DP Ref No. 0588824

₱ 2,000.00