

JANUARY 17, 2020

BELTRAN, FERDINAND
UNIT 3518 GRAND EMERALD TOWER, GERNET ROAD
BRGY. SAN ANTONIO PASIG CITY
0917-8717435

Sir/Ma'am:

Kindly see the quotation below for more details.

MODEL: KAG-100HRE4

SJR: HO-5593

Repair Code	Repair Done	Labor
WAC02	General Cleaning	750.00
	Total:	750.00

Total Initial Charge:

P 750.00

Note:

1. Unit For General Cleaning.
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at **852-6868 or 0917-806-0920**.
5. Once quotation is confirmed 50% downpayment needs to be deposit before proceeding for repair. However, problem(s) may occur once after or during replacement of part(s).
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before installing the unit.
7. Confirmation must be complied on or before 2 days otherwise your unit will be delivered back to you.
8. Initial Quotation.

Prepared by:

ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:

JOEL CORIA
SHOP FOREMAN

Verified by:

BRYAN JED O. ARCILLA
SERVICE ACCOUNTING ASST.

Conforme:

Ferdinand E. Beltran Jr.
SIGNATURE OVER PRINTED NAME

5:24 PM

01/17/2020

NO DOWNPAYMENT

Head Office:

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
www.kolinphil.com.ph

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant:

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy.
Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793