



MR. EFREN CHUA YAP
Malate Bayview Mansion Unit 10-P
1781 M. Adriatico, Malate Manila

SEPTEMBER 18, 2019

MALATE BAYVIEW MANSION UNIT 10-P
1781 M. ADRIATICO, MALATE MANILA
GO TO ADMIN OFFICE @ 7TH/FLR LUK 4-PRINCESS 536-0033
523-0170

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KAG-190RE

APRIL 2013 ~~Purchased~~

SJR: 0593847

Parts
Overload Protector
Compressor
Compressor Capacitor
Compressor leadwire
Fan Capacitor
System Reprocess
Pull Out Delivery
Total:

Amount

210.00

8,500.00

385.00

220.00

220.00

2,000.00

~~500.00~~

11,825.00

978

less 20%

- 1960 = 7460

+ 1,800

P 9,260 + 210

Total Estimated Charge:

P 11,825.00

Note:

1. Replacement Of Compressor, Comp. Cap, Comp. Leadwire, Fan Capacitor.
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (Parts & Labor) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (Angel Arlan De Torres) at 852-6868 or 0917-806-0920.
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair.
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. Initial Quotation.

Prepared by:

ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:

JOEL CURIA
SHOP FOREMAN

Conforme:

SIGNATURE OVER PRINTED NAME

Head Office:

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

www.kolinphl.com.ph

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant:

Blk 8 Lt 5 Main Drive, FCE Compound, Brgy.

Langkaan J, Daanparais, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793

9:37 AM

9.24.19