

kolin

Kolin Philippines International Inc.
1854 Sta. Rita St., Guadalupe Nuevo
Makati City
Tel. No. 852-6868

BILLED

SERVICE JOB REPORT

No. 0583847
Backjob SJR No.

Customer	MALATE BAYVIEW MANSION (UNIT 10-P)			DATE: 9/12/19 10:02	Date	09/13/2019
Address	1781 M. ADRIATICO, MALATE MANILA			BILLED 9/13/19 8:39	Time	04:18 pm
GO TO ADMIN OFFICE @ 7TH/FLR LUK4-PRINCESS					Relayed by	
Tel. No.	523-0170	Date of Purchase		Dealer		
Model	KAG-190RE	Serial No.	NO SERIAL	Warranty Type	C	
Complaint	AC20 - Not Cooling			Job Class	TS	
Remarks	4SHOP REPAIR(PORR#1339, CHECKLIST#001230)			Job Type	PO	
SR No.		Materials	☐ Used ☐ Needed			
Part No.	Description	Qty.	Unit Price	Amount		
BR501K6620B1	Compressor	1	8,500.00	8,500.00		
BR33000027	Compressor Capacitor	1	385.00	385.00		
BR1020005	Fan Capacitor (7 uf)	1	220.00	220.00		
TK1903915600	Compressor Leadwire	1	220.00	220.00		
TK081706300	Over load Protector	1	210.00	210.00		
Findings	(S) Defective Compressor / CompCap / FanCap / L-Wire / OLP			Labor	2,000.00	
	less 20% parts: 1,907.00			7,628.00	Handling	0.00
Repair Done	System Reprocess			less 10% labor: 200.00	1,800.00	Total
Repair Code	WAC49			Balance: 9,428.00	Amount Paid	0.00
Date Attended	09/12/2019	Date Finished	09/26/2019	Balance	11,535.00	
Time Attended	13:06	Time Finished	19:00	Check No.		
This serves as temporary receipt when properly filled up by authorized representative				I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.		
Served by: Elecho, L.		Evaluated by: RUBEN		Customer		
Technician		CRA/Supervisor		(Signature over printed name)		