

SEPTEMBER 26, 2019

PAYUMO, FERNANDO

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KSM-100B1E

SJR: 0584814

Parts	Amount
Fan Capacitor (I)	165.00
Fan Capacitor (O)	165.00
Overload Protector	210.00
Compressor Leadwire	220.00
System Reprocess	3,000.00
Pull Out Delivery	<u>500.00</u>
Total:	4,260.00

Total Estimated Charge:

P 4,260.00

## Note:

1. *Replacement Of Fan Capacitor (I) & (O), Overload Protector, Compressor Leadwire.*
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at *852-6868 or 0917-806-0920.*
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair.
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. *Initial Quotation.*

Prepared by:

  
ANGEL ARLAN DE TORRES

Noted by:

  
JOEL CORIA  
SHOP FOREMAN

Conforme:

*Via Email / 10.3.19 / 2:34 PM*  
SIGNATURE OVER PRINTED NAME

Kolin Plant:

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy,  
Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793

Sent Quotation ok  
9/26/19 2:20 PM