

OCTOBER 8, 2019

UKWATTE, REGINA
B-4 L11 2-B CTUDAD DEL CARMEN
C. RAYMUND ROSARIO PASIG 0917-8025596
643-3478

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KAG-08RE

SJR: 0586893-

Parts	Amount
Bearing	440.00
Evaporator	2,244.00
Fan Capacitor	165.00
Compressor Capacitor	330.00
System Reprocess	2,000.00
Pull Out Delivery	500.00
Total:	5,679.00

Total Estimated Charge:

P 5,679.00

Note:

1. Replacement Of Evaporator, Fan Capacitor, Compressor Capacitor.
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at **852-6868 or 0917-806-0920.**
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair. However, problem(s) may occur once after or during replacement of part(s).
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. *Initial Quotation.*

Less 10% on Actual Charges
d/o Sir-Pluin

P 5,111.10

Less DP:

P 2,000.00

Balance: P 3,111.10

Prepared by:

ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:

JOEL CORIA
SHOP FOREMAN

Conforme:

Via Email / 9:29 PM / 10:22.19

SIGNATURE OVER PRINTED NAME