

SEPTEMBER 24, 2019

NISPEROS, DEXTER
7901 GONZALES ST. GUADALUPE VIEJO MAKATI
0998-5942951 8639-9378
698-9378

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KAG-150HRE4

SJR: 0588961

Parts	Amount
General Cleaning	750.00
Pull Out Delivery	<u>500.00</u>
Total:	1,250.00
Total Estimated Charge:	P <u><u>1,250.00</u></u>


Note:

1. *Unit For General Cleaning.*
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at **852-6868 or 0917-806-0920.**
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair. However, problem(s) may occur once after or during replacement of part(s).
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. *Initial Quotation.*

Prepared by:


ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:


JOEL CORIA
SHOP FOREMAN

Conforme:

Via Email / 12:42 PM / 10.25.19


SIGNATURE OVER PRINTED NAME

IV/DP

9:28am