

OCTOBER 29, 2019

RUIZ, RONNIE
1854 STA RITA ST. GUADALUPE NUEVO MAKATI
0917-8118962

Sir/Ma'am:

Please find below the quotation for repair of the following unit.

MODEL: KAG-08ME

SJR: 0590071

Parts	Amount
Evaporator	2,244.00
Metal Partition (Con-Side)	550.00
Compressor Capacitor	330.00
Fan Capacitor	165.00
System Reprocess	2,000.00 - 10%
Total:	5,289.00

Total Estimated Charge:

P 5,289.00

Note:

1. Replacement of Evaporator, Metal Partition, Compressor Capacitor.
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (Parts & Labor) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (Angel Arlan De Torres) at 852-6868 or 0917-806-0920.
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding the repair
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. Initial Quotation.

Net : Php 4,000

Prepared by:

ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:

JOEL CORIA
SHOP FOREMAN

Conforme:

SIGNATURE OVER PRINTED NAME

Head Office:

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

www.kolinphil.com.ph

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant:

Bldg 3 Lt 5 Main Drive, FCIE Compound, Brgy.

Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793

8:14 am