

JANUARY 22, 2020

CHING, BEN
81 LINAO ST. BRGY. SIENNA, QUEZON CITY
0915-5333244

Sir/Ma'am;

Kindly see the quotation below for more details.

MODEL: KDM-20LES

SJR: HO-5911

Part Code:	Parts Description	Qty	Amount	Total Amount
MD12120100000125	Base Pan	1	700.00	700.00
Repair Code	Repair Done	Labor		
KSM02	Labor			800.00
	Total:			1,500.00

Total Initial Charge:

P 1,500.00


Note:

1. **Replacement Of Base Pan.**
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (**Parts & Labor**) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (**Angel Arlan De Torres**) at **852-6868 or 0917-806-0920.**
5. Once quotation is confirmed 50% downpayment needs to be deposit before proceeding for repair. However, problem(s) may occur once after or during replacement of part(s).
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before installing the unit.
7. Confirmation must be complied on or before 2 days otherwise your unit will be delivered back to you.
8. **Initial Quotation.**


Prepared by:


ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:


JOEL CORIA
SHOP FOREMAN

Verified by:


BRYAN JED O. ARCILLA
SERVICE ACCOUNTING ASST.

Conforme:


SIGNATURE OVER PRINTED NAME

NO DOWNPAYMENT