

FEBRUARY 5, 2020

ALIPANTE, BHING
B-10 LOT 6, LA TRINIDAD VILLAGE BRGY. TALIPAPA
QUEZON CITY METRO MANILA
0917-8824646

Sir/Ma'am;

Kindly see the quotation below for more details.

MODEL: KAG-150RSINV

SJR: HO-8172

Part Code:	Parts Description	Qty	Amount	Total Amount
	Service unit Fee	1	150.00	150.00
Repair Code	Repair Done	Labor		
WAC02	General Cleaning			800.00
HND02	Pulled-out Delivery			500.00
	Total:			1,450.00

Total Initial Charge: P 1,450.00

Note:

1. *Unit For General Cleaning.*
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at **852-6868 or 0917-806-0920.**
5. Once quotation is confirmed 50% downpayment needs to be deposit before proceeding for repair. However, problem(s) may occur once after or during replacement of part(s).
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before installing the unit.
7. Confirmation must be complied on or before 2 days otherwise your unit will be delivered back to you.
8. *Initial Quotation.*

Prepared by: 
ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:

JOEL CORIA
SHOP FOREMAN

Verified by:

BRYAN JED O. ARCILLA
SERVICE ACCOUNTING ASST.

Conforme:


SIGNATURE OVER PRINTED NAME