

FEBRUARY 11, 2020

CASTRO II, RAMON A.
4301 BLISS DAVILA ST.,
STA. CRUZ, MANILA CITY
0906-5090079

Sir/Ma'am;

Kindly see the quotation below for more details.

MODEL: KAG-11RE

SJR: HO-9173

Part Code:	Parts Description	Qty	Amount	Total Amount
GR30032791	PCB (IC Type)	1	1,760.00	1,760.00
GR30542892	Display Board 2891J/XSB2891AJ dual socket	1	385.00	385.00
GR33010021	Capacitor 3uF/450V	1	165.00	165.00
Repair Code	Repair Done			Labor
WAC04	General cleaning with major repair			1,350.00
	Total:			3,660.00

Total Initial Charge: P 3,660.00

Note:

1. Upon receiving a quotation, please check the details. To proceed with the repair we need your confirmation with 50% downpayment.
2. Kindly reminded that you must comply in 2 working days otherwise your unit will be considered refuse to repair hence, your unit will delivered back un-repaired with fitting charges.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. Please be informed that upon delivery and installation of your unit the remaining balance of 50% shall be paid our installer or technician.
5. If you need assistance and update don't hesitate to call the under signed (*Angel Arlan De Torres at (8)962-5610 or 0917-806-0920*).
6. For replacement of PCB, Display Board and Capacitor.
7. Initial Quotation.

Prepared by:

BRYAN JED O. ARCILA
SERVICE ACCOUNTING ASST.

Noted by:

JOEL U. CORIA
SHOP FOREMAN

Received by:

ANGEL ARLAN A. DE TORRES
SHOP ASSISTANT

Conforme by:

CUSTOMER NAME
SIGNATURE OVER PRINTED NAME

1/2 Email / 2. 12.28 / 3.51 PM

Balance P 1,660.00