

SEPTEMBER 26, 2019

ALVARADO, JASMINE  
06 DIMASALANG ST. BRGY. HAGONoy TAGUIG  
839-9193/ 0945-7917088  
791-6129

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KAG-80DRE

SJR: 0585230

Parts	Amount
Evaporator	2,244.00
System Reprocess	2,000.00
Pull Out Delivery	<u>500.00</u>
Total:	4,744.00

Total Estimated Charge:

P 4,744.00


**Note:**

1. *Replacement Of Evaporator.*
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at *852-6868 or 0917-806-0920.*
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair.
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. *Initial Quotation.*

Prepared by:

  
ANGEL ARLAN DE TORRES  
SHOP ASSISTANT

Noted by:

  
JOEL CORIA  
SHOP FOREMAN

Conforme:

*Via Email/10:44 AM*

SIGNATURE OVER PRINTED NAME

Email: *jhazery1520@gmail.com*

*Sent Quotation / 9.26.19*

*11:28*

*10:58*