

NOVEMBER 12, 2019

BRIONES, MERYLL
CREEK DRIVE 2 SAN JUAN PASCUAL ST. SAN ANTONIO
VALLEY 8 PQUE 0915-4616389/ 0915-706125
0915-4646389

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KAG-60DME

SJR: 0582777

Parts	Amount
Evaporator	2,200.00 <i>why</i>
System Reprocess	2,000.00
Pull Out Delivery	<u>500.00</u>
Total:	4,700.00
Total Estimated Charge:	P <u>4,700.00</u>

Note:

1. *Replacement Of Evaporator*
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at 852-6868 or 0917-806-0920.
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair.
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. *Initial Quotation.*

Prepared by:

Angel Arlan De Torres
ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:

Joel Coria
JOEL CORIA
SHOP FOREMAN

Conforme:

Via Email / 11.12.20 / 10:48 AM
SIGNATURE OVER PRINTED NAME

Head Office:

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

www.kolinphil.com.ph

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant:

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy,

Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793