

SEPTEMBER 30, 2019

DE LEON, SHARON
1451 UNION ST. PACO MANILA
0919-9461400 LOOK 4 ARIEL DE GUZMAN

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KAG-150DRE

SJR: 0585602

Parts	Amount
Transformer	550.00
PCB	880.00
Compressor Capacitor	385.00
Fan Capacitor	165.00
Labor	1,250.00
Total:	3,230.00

Total Estimated Charge:

P 3,230.00

Note:

1. *Replacement Of PCB, Compressor Capacitor, Fan Capacitor.*
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at **852-6868 or 0917-806-0920.**
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair.
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. *Initial Quotation.*

DP: ₱1,600

Balance: ₱1,630.00

Prepared by:


ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:

JOEL CORIA
SHOP FOREMAN

Conforme:

Via Email / 10.1.19 / 10:23 pm

SIGNATURE OVER PRINTED NAME