

OCTOBER 30, 2019

MEDISENSE LABORATORY CENTER INC.
3F/5F BDO BUILDING T.M. KALAYAAN AVE. COR.
CHURUCCA ST. ERMITA MANILA 401-6181
855-5857

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KFM-7001E

Parts

- / Discharge Sensor
- / Compressor
- / Condenser
- / Evaporator
- Compressor Leadwire
- / Pressure Switch (High Side)
- / Pressure Switch (Low Side)
- / Fan Capacitor
- / Anti Freeze
- System Reprocess
- Pull out Delivery
- Total:

SJR: 0590064

Amount

380.00

0.00

6,600.00

4,950.00

0.00

330.00

1,100.00

330.00

1,100.00

275.00

330.00

0.00

0.00

12,815.00

17,685.00

Total Estimated Charge:

P 12,815.00

DO

Cash Transaction Slip

Deposits
Current Savings
Time Deposit/
Placement
☐ For Account
With Deposit
Reference
Facility

Is Payment

Cash Card
Sale ☐ Reload
Payment ☐ Loan ☐ Trade

Validation

Account Name
Account No.
Payor's Name
Company Name
Subscriber's Name
Cardholder's Name/Contact No.
Borrower's Name

Reference No.
Institution Code
Subscriber's Account No.
Cash Card No.
Promissory Note No. / Trade Reference No.

Currency
☐ Peso ☐ US Dollar ☐ Others

Date

Use separate slip(s) for each type of transaction.

Denomination	Pieces	Amount
100	12	1,200.00
500	1	500.00
10	8	80.00
5	3	15.00
Total Cash In		1,795.00
Total Cash Out		0.00
Total Amount		1,795.00

011508000428

Cash In: 12,815.00

Ref#: 0590064

Date: 31 Oct 2019 31-10-19 14:55:36

Override ID:

This serves as your receipt when machine validated.

V032018

Tel: (632) 851-2711 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Tel.: (632) 749-2118

Fax: (046) 402-0793

Confirm: Nidesango 10.31.19/17.40