

OCTOBER 15, 2019

GERICKED, BERND
UNIT 2409 ROCKWELL CENTER MAKATI CITY
0916-2377568
0916-2377568

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

Model: KDM-20DGS


SJR: 0546140

Parts	Amount
Evaporator	1,100.00
System Reprocess	1,500.00
Total:	2,600.00
Total Estimated Charges:	P <u>2,600.00</u>

Note:

1. *Replacement of Evaporator.*
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at **8852-6868 or 0917-8060920**
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair. However, problem(s)
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. *Initial Quotation.*


Prepared by:


ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:


ANGEL ORNIDO
TECHNICIAN III

Conformer:


SIGNATURE OVER PRINTED NAME

B Gerick

10/15/2019
4:29 PM

Head Office:

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
www.kolinphil.com.ph
Tel.: (632) 851-2711, 12 or 15
Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant:

Bldg 3 Lt 5 Main Drive, FCIE Compound, Brgy.
Langkaan I, Dasmarinas, Cavite
Tel.: (632) 749-2118
Fax: (046) 402-0793