

DECEMBER 2, 2019

GRS UNITED INSURANCE AGENCY & CONSULTANCY
 2-61231TH AND 10 TOWER 2 1540 E.V. DELA COSTA
 ST. REG. AIRC. MAKATI 0932-6541818
 519-0290

Sir/Ma'am,

Please find below the quotation for repair of the following unit.

MODEL: KAG-210RS

SJIP: 0594218

Parts

Amount

Metal partition (Condenser Side)

1,000.00

Fan Capacitor

220.00

Labor: Reprocess

1,000.00

Total

2,220.00

Total Estimated Charge:

2,220.00

Note:

1. Replacement Of Metal Partition, Fan Capacitor.
 2. Final charges will be based on actual repair of unit.
 3. Repaired units are guaranteed for a period of 90 days (Parts & Labor) from date of unit acceptance and for the same encountered defects.
 4. If you need assistance don't hesitate to call the under signed (Angel Arlan De Torres) at 852-6868 or 0917-806-0920.
 5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair. However, problem(s) may occur once after or during replacement of part(s).
 - The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
- Initial Quotation.

Prepared by

ANGEL ARLAN DE TORRES
 SHOP ASSISTANT

Noted by

JOEL CORIA
 SHOP FOREMAN

Conforms

HAROLD B. DEYON
 SIGNATURE OVER PRINTED NAME

Head Office

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

www.kolinphil.com.ph

Tel: (632) 851-2711, 12 or 15

Kolin Plant

Bldg 3 Lt 5 Main Drive, FCB Compound, Brgy.

Langkaan I, Orosarinas, Cavite

Tel: (632) 749-2118

12.11.19 / 1:37