

DECEMBER 11, 2019

ICCT COLLEGES (CAINTA BRACH)
V.V. SOLIVEN AVE. II CAINTA RIZAL
249-1176/ 0917-5709049 0977-3836863
682-5914

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KSG-36C1M		SJR: 0594312
Parts		Amount
Compressor Capacitor		440.00
Compressor Leadwire		550.00
Anti Freeze		330.00
Fan Capacitor 4mf		165.00
Fan Capacitor 3.5mf		165.00
ADDITIONAL — [Pressure valve 3/8		1,061.50
Pressure valve 3/4		1,540.00
System Reprocess		3,500.00
Pull Out Delivery		<u>500.00</u>
Total:		8,251.50
Total Estimated Charge:	P	<u>8,251.50</u> Less 10%

Note:

1. Replacement Of Compressor Capacitor, Compressor Leadwire, Anti Freeze, Fan Capacitor (I) & (O), Pressure valve 3/8x5/8.
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (Parts & Labor) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (Angel Arlan De Torres) at 852-6868 or 0917-806-0920.
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair.
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. Initial Quotation.

Prepared by:

ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:

JOEL CORIA
SHOP FOREMAN

Conforme:

SIGNATURE OVER PRINTED NAME

Head Office:

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
www.kolinphil.com.ph

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant:

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy.
Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793