

OCTOBER 17, 2019

JAMLA CORP. 151 PINATUBO ST. BARANGKA ILAYA MANDALUYONG 0905-8838205 0906-2393338 747-3138

Sir/Ma'am;

Please find below the quotation for repair of the following unit,

Model: KDM-20DGS		S	JR: 0587896
Parts			Amount
Evaporator			1,100.00
System Reprocess			1,500.00
Total:			2,600.00
Total Estimated Charge:		Р	2,600,00

Note:

- Replacement Of Evaporator.
- 2. Final charges will be based on actual repair of unit.
- 3. Repaired units are guaranteed for a period of 90 days (Purts & Lubor) from date of unit acceptance and for the same encountered defects.
- 4. If you need assistance don't hesitate to call the under signed (Angel Arlan De Torres) at 852-6868 or 0917-806-0920.
- 5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair. However, problem(s) may occur once after or during replacement of part(s).
- 6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.

7. Initial Quotation.

Prepared by:

ANGEL AREAN DE TORRES SHOP ASSISTANT Noted by:

10/17/1

JOEU CORTA SHOP FOREMAN

Conforme:

norme:

JESSA LI LA

SIGNATURE OVER PRINTED NAME

10/21/2015

Head Office.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City www.kolinphil.com.ph

Tel. (832) 851-2711, 12 or 15

Fax. (632) 852-2170 / Sales Dept. Fax. (632) 852-4791

Kolin Plant:

Bik 3 Lt 5 Main Drive, FCIE Compound, Brgy, Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax. (046) 402-0793