

SEPTEMBER 19, 2019

LIM, KENNETH
 PASELLO 188 MANILA TEXTILE MARKET CLARO
 M. RECTO ST. BINONDO MANILA 0917-8270523
 244-0105

Sir/Ma'am:

Please find below the quotation for repair of the following unit.

KAG-110RSINV

SJR: 0583828

Parts	Amount
General Cleaning	750.00
Pull Out Delivery	500.00
Total:	1,250.00
Total Estimated Charge:	P <u>1,250.00</u>

Note:

1. Unit For General Cleaning.
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (Parts & Labor) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (Angel Arlan De Torres) at 852-6868 or 0917-806-0920.
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair.
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. Initial Quotation.

Prepared by:

ANGEL ARLAN DE TORRES
 SHOP ASSISTANT

Noted by:

JOSE CORIA
 SHOP FOREMAN

Conforme:

SIGNATURE OVER PRINTED NAME