

SEPTEMBER 13, 2019

MEDINA, GERONIMO
B9 L9 KENSINGTON VILL KENSINGTON 3
BRGY. NAVARRO GEN. TRIAS CAV. 0945-5821670
402-6027

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KSM-IW10AE-5G1M

SJR: 0583477

Parts	Amount
Compressor	0.00
PCB (O)	5,500.00
System Reprocess	3,500.00
Pull Out Delivery	<u>500.00</u>
Total:	9,500.00

Total Estimated Charge: P 9,500.00

Note:


1. *Replacement of Compressor, PCB(O).*
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at 852-6868/ 962-5610 or 0917-8060920.
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding the repair
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. *Initial Quotation*

Prepared by:


ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:


JOEL CORIA
SHOP FOREMAN


MR. RONNIE RUIZ

NATIONAL SERVICE MANAGER
Head Office:


1854 Sta. Rita St., Guadalupe Nuevo, Makati City

www.kolinphil.com.ph

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Conforme:

 *CONSIDERED W/ty 9.17.19/2:30*
SIGNATURE OVER PRINTED NAME

Kolin Plant:

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy.

Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793