

OCTOBER 30, 2019

MEDISENSE LABORATORY CENTER INC.
3F/5F BDO BUILDING T.M. KALAYAAN AVE. COR.
CHURUCCA ST. ERMITA MANILA 401-6181
855-5857

Sir/Ma'am:

Please find below the quotation for repair of the following unit.

MODEL: KFM-7001E

SJR: 0590064

Parts	Amount
Compressor	0.00
Condenser	6,600.00
Evaporator	4,950.00
Compressor Leadwire	0.00
Pressure Switch (High Side)	1,100.00
Pressure Switch (Low Side)	1,100.00
Fan Capacitor	275.00
Anti Freeze	330.00
Discharge Sensor	330.00
System Reprocess	0.00
Pull out Delivery	0.00
Total:	14,685.00

Total Estimated Charge:

P 14,685.00


Note:

1. *Replacement of Compressor, Condenser, Evaporator, Comp. Leadwire, Fan Cap 10mf Pressure Switch (H) & (L) Side, Anti Freeze*
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at *852-6868 or 0917-806-0920*.
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding the repair
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. *Initial Quotation.*

Prepared by:


ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:


JOEL CORIA
SHOP FOREMAN

Conforme:


Aries Tynne Stella

SIGNATURE OVER PRINTED NAME

Head Office:

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

www.kolinphil.com.ph

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4704

Kolin Plant:

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy,

Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0702