

OCTOBER 17, 2019

MOZO, ELBERT  
U-1624A TOWER 1 GRASS RESIDENCES BRGY.  
STO CRISTO QUEZON CITY 0917-8012297  
211-9020

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KSM-15CB1INV

SJR: 0588501

Parts	Amount
Anti Freeze	220.00
Fan Motor (I)	1,650.00
PCB (I)	2,750.00
Blower Wheel	1,100.00
Compressor Capacitor	385.00
Fan Capacitor	165.00
System Reprocess	3,500.00
Pull Out Delivery	<u>500.00</u>
Total:	10,270.00

Check up Fee: 450.00

Delivery: 500.00

950.00

Total Estimated Charge:

P 10,270.00

**Note:**

1. Replacement Of Anti Freeze, Fan Motor(I), PCB (I), Blower Wheel, Comp. Cap, Fan Cap.
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (**Parts & Labor**) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (**Angel Arlan De Torres**) at **852-6868 or 0917-806-0920**.
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair. However, problem(s) may occur once after or during replacement of part(s).
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. Initial Quotation.

Prepared by:

Noted by:

JOEL CORIA

SHOP FOREMAN

Conform:

Kolin SIGNATURE OVER PRINTED NAME

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy,

Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793

Sent Quotation ok

10.17.19 / 3:09