

kolin

air conditioner

OCTOBER 31, 2019

PO, ANTONIO
B1 L36 CITHOMES SUBD. MANUYO LAS PIÑAS
0905-5230315 0917-8639799/ 0915-2428304
829-7206

Sir/Ma'am:

Please find below the quotation for repair of the following unit.

KAG-08RE

SJR: 0590062

Parts	Amount
Metal Partiton Condenser Side	550.00
Compressor Capacitor	385.00
Labor	1,250.00
Pull out Delivery	500.00
Total:	2,685.00
Total Estimated Charge:	P <u>2,685.00</u>

Note:

1. *Replacement of Metal Partition Con-side, Compressor Capacitor.*
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at 852-6868 or 0917-806-0920.
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding the repair
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. *Initial Quotation.*

Prepared by

ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by

JOEL CORIA
SHOP FOREMAN

Conforme:

SIGNATURE OVER PRINTED NAME

Head Office:

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
www.kolinphd.com.ph
Tel.: (632) 851-2711, 12 or 15
Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant

Bix 3115 Main Drive, FCI Compound, Pinar
Lingayon I, Dasmariñas, Cavite
Tel.: (032) 749-2118
Fax: (032) 402-0793