

SEPTEMBER 10, 2019

MORILES, MERCEDITA
#3 MEADWOOD AVE. MEADOEW EXEC. VILLAGE
PANAPAAN BACOR CAVITE 0918-9090664
0949-5872016
Sir/Ma'am:

Please find below the quotation for repair of the following unit.

MODEL: KSM-20MB11N

25781158

Parts	Amount
Compressor	3,000.00
System Re-process	3,500.00
Pull Out Delivery	500.00
Total:	4,000.00
Total Estimated Charge:	P 4,000.00

Note:

1. Replacement Of Compressor.

2. Final charges will be based on actual repair of unit.

3. Repaired units are guaranteed for a period of 90 days (Parts & Labor) from date of unit

acceptance and for the same encountered defects.

4. If you need assistance don't hesitate to call the under signed (Angel Arlan De Torres) at

852-6868 or 0917-806-0920.

5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair.

However, problem(s) may occur once after or during replacement of part(s).

6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.

7. Initial Quotation.

Prepared by: *[Signature]*
ANGEL ARLAN DE TORRES
SHOP ASSISTANT
9-10-19

Noted by: *[Signature]*
JOEL CORIA
SHOP FOREMAN
09-10-2019

Conforme: *[Signature]*
SIGNATURE OVER PRINTED NAME
9-10-19 / 4:02 PM

Head Office:
1854 Sta. Rita St., Guadalupe Nuevo, Makati City
www.kolinphl.com.ph
Tel.: (632) 851-2711, 12 or 15
Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791
Kolin Plant:
BIK 3 Lt 5 Main Drive, FCIE Compound, Brgy.
Langkaan I, Dasmariñas, Cavite
Tel.: (632) 749-2118
Fax: (046) 402-0793