

SEPTEMBER 5, 2019

SIDDAYAO, EMILY O.
11 ROOSEVELT ST. WEST GREENHILLS SAN JUAN
241-0352 / 0917-8955108 / 0915-4432434 / 0935-4238969
721-0677

Sir/Ma'am:

Please find below the quotation for repair of the following unit.

MODEL: KAG-190DRE

SJR: 0582149

Parts	Amount
Evaporator	3,850.00
Bearing (6201)	440.00
System Recharge	2,000.00
Total:	<u>6,290.00</u>
Total Estimated Charge:	P <u>6,290.00</u>

DP: ₱ 3,000.00

Balance: ₱ 3,290.00

Note:

1. Replacement Of Evaporator, Bearing
2. Total charges will be paid for actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (Parts & Labor) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (Angel Arlan De Torres) at 852-6868 or 0917-806-0920.
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair.
6. The remaining balance after 50% downpayment is to be paid to Kolin technician before install the unit.

Initial Quotation.

Prepared by:

ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:

JOEL CORIA
SHOP FOREMAN

Confirme:

Via Email / 9.11.19 / 9:56 AM

SIGNATURE OVER PRINTED NAME

Head Office

1534 Sta. Rita St. Goodolube Nuevo, Makati City
www.kolinphil.com.ph

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant

316 316 Main Drive FCIF Compound, Brgy.
Lagkasan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793