

SEPTEMBER 20, 2019

TAN, MCNIEL/ SUSIE  
#1737 SAN ARCELINO ST. MALATE MANILA  
524-9326/ 0917-8571509/ 0917-5290294  
524-9326

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KSG-20B1

SJR: 0583475

Parts	Amount
<b>Overload Protector</b>	<b>210.00</b>
Compressor Capacitor	385.00
Compressor Leadwire	220.00
Fan Capacitor	165.00
System Reprocess	3,000.00
Pull Out Delivery	<u>500.00</u>
Total:	4,270.00

Total Estimated Charge:

P 4,270.00

Note:

1. Replacement of Evaporator, Compressor Capacitor, Compressor Leadwire, Fan Capacitor.
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at 852-6868/ 962-5610 or 0917-8060920.
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding the repair
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. Initial Quotation

DP: ₱2,135.00

Prepared by:

ANGEL ARLAN DE TORRES  
SHOP ASSISTANT

Noted by:

JOEL CORIA  
SHOP FOREMAN

Conforme:

Via Email/ 9.24.19/ 10:43 PM

SIGNATURE OVER PRINTED NAME

Head Office:

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

www.kolinphil.com.ph

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant:

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy,

Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793