

OCTOBER 28, 2019

TAN, STEVE
#3121 LABUCAY ST. COR. HERMOSA ST.
TONDO MANILA 0917-8440000/ 252-6208/ 216-2324
252-6207

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KAG-260RS

SJR: 0562538

Parts	Amount
Evaporator	3,300.00
System Reprocess	2,000.00
Service Unit Fee:	250.00
Pull out Delivery	<u>500.00</u>
Total:	6,050.00

Total Estimated Charge:

P 6,050.00


Note:

1. *Replacement of Evaporator.*
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at **852-6868 or 0917-806-0920.**
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding the repair
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. *Initial Quotation.*

Prepared by:


ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:


JOEL CORIA
SHOP FOREMAN

Conforme:

Via Email/11.7.19/1:58PM

SIGNATURE OVER PRINTED NAME

W/Downpayment